

618/345-0700  
115A West Main Street  
Collinsville, Illinois 62234

Refer to: Madison County - 11909001 - Roxana/SCA-Barton

February 8, 1979

SCA Services of Illinois, Inc.  
401 Madison Avenue  
Madison, Illinois 62060



Gentlemen:

Your solid waste disposal facility located between Roxana and Edwardsville, Illinois was inspected on January 29, 1979, by Dave Wietes, representing this Agency.

Sandy Pence was contacted at the time of the inspection.

The inspection disclosed the following condition(s) which constitute violations of the Environmental Protection Act and Chapter 7 of the Illinois Pollution Control Board Solid Waste Rules and Regulations:

... Previously deposited solid waste was observed protruding through the snow. All solid waste received daily must be covered with a minimum of six (6) inches of compacted suitable natural earth cover.

... An inadequate depth of daily cover was observed in an area located on the fill face.

... Final cover has not been applied on the completed portions of your fill as prescribed in the Solid Waste Rules and Regulations. A compacted layer of not less than two (2) feet of suitable natural earthen material shall be placed over the entire surface of each portion of the final lift not later than 60 days following the placement of solid waste in the final lift, unless a different schedule has been issued in the operating permit.

... Solid Waste was being deposited at the top of the fill face. Solid waste should be deposited into the toe of the fill or into the bottom of the trench unless otherwise indicated in your permit.

... A large bird population was observed. Daily cover of refuse would alleviate this potential health hazard.

It is suggested that you take immediate steps to resolve the conditions described above.

Page 2

You must not accept the barrel contained pharmaceutical wastes from Mallinckrodt until a trench operation plan change has been submitted and approved.

Sincerely,

Kenneth G. Mensing, Southern Region Manager  
Land Field Operations Section  
Division of Land/Noise Pollution Control

KGM:DLW:bls/6141/24-25

Enclosure: Inspection Report

cc: Division File  
Southern Region

Previously reported solid waste was observed at the site. All solid waste received daily must be covered with a minimum of (6) inches of cover to protect the natural earth cover.

An irregular depth of daily cover was observed in an area located on the fill face.

Thin daily cover has not been applied on the completed portions of your fill area. The top of the solid waste must be completely covered. A complete layer of refuse is required at least one inch thick. The surface of the solid waste must be completely covered with a minimum of (6) inches of cover. The cover must be applied to the entire surface of the solid waste.

Solid waste was being deposited at the top of the fill face. Solid waste should be deposited into the bottom of the trench until it is full. Solid waste should be covered with a minimum of (6) inches of cover.

A large bird population was observed. Daily cover of refuse would alleviate this potential health hazard.